

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Prairie States Coop PO Box 6 Zahl ND 58856 Phone: (701) 694-4111

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4600762	Prairie States Coop Terminal	Main St PO Box 338	Dagmar	59219	(406) 483-5297

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																									
Status		Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																									
6 / S6	4500	11/1/2001	Diesel	Unknown	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
Currently In Use		04 / Ye	15,000	None	Double-Walled			Yes Yes Yes																									
7 / S7	4501	11/1/2001	Diesel	Unknown	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
Currently In Use		04 / Ye	15,000	None	Double-Walled			Yes Yes Yes																									
8 / S8	4502	11/1/2001	Gasoline	Unknown	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
Currently In Use		04 / Ye	15,000	None	Double-Walled			Yes Yes Yes																									

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Herman Oil Co 403 47th St W Williston ND 58801 Phone: (701) 572-2478

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4611342	Herman Oil Inc Homestead		Homestead	59242	(406) 789-2242

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 02 Currently in Use	2328	1/1/1990 16 / No	Gasoline 2,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>			D	E	F	G	H	I	J	K	L																					
2 / 01 Currently in Use	2327	1/1/1990 16 / No	Diesel 2,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>			D	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Medicine Lake School Dist 7 PO Box 265 Medicine Lake MT 59247 Phone: (406) 789-2211

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4601122	Medicine Lake School Dist 7	1 Young St	Medicine Lake	59247	(406) 789-2211

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S3 Currently In Use	1603	8/1/1991 14 / No	Heating Oil 10,066	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B G E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B G E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Herman Oil Co 403 47th St W Williston ND 58801 Phone: (701) 572-2478

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4601127	Herman Oil Inc Medicine Lake	MT Highway 16 & Main St	Medicine Lake	59247	(406) 789-2242

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / S6 Currently in Use	2323	10/1/1997 08 / Ye	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
7 / S7 Currently in Use	2324	10/1/1997 08 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
8 / S8 Currently in Use	2325	10/1/1997 08 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
9 / S9 Currently in Use	2326	10/1/1997 08 / Ye	Gasoline 8,000	Unknown None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Outlook School Dist 29 PO Box 296 Outlook MT 59252 Phone: (406) 895-2465

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4600157	Outlook School Dist 29	Wirtz St	Outlook	59252	(406) 895-2465

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S2 Currently in Use	1779	1/15/1991 15 / No	Heating Oil 10,000	Polyethylene Tank Jacket Double-Walled	Copper Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Sheridan Memorial Hospital 440 W Laurel Ave Plentywood MT 59254 Phone: (406) 765-1420

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4600795	Sheridan Memorial Hospital	440 W Laurel Ave	Plentywood	59254	(406) 765-1420

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / S3 Currently In Use	1918	10/1/1998 07 / No	Heating Oil 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Raymond J Forster 327 W 1st Ave Plentywood MT 59254 Phone: (406) 765-1180

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4601524	Auto Tech Services	327 W 1st AVE	Plentywood	59254	(406) 765-1180

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
8 / 08 Currently in Use	1114	12/10/1989 16 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently in Use	1115	12/10/1989 16 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
10 / 10 Currently in Use	1116	12/10/1989 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Krause Gentle Corporation 6400 Westown Pkwy West Des Moines IA 50266 Phone: (515) 226-0128

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4605200	Kum and Go Store 808	211 W 1st Ave	Plentywood	59254	(406) 765-2847

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	1498	12/1/1982 23 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	4358	1/1/1988 18 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1500	1/1/1988 18 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Sheridan County 100 W Laurel Ave Plentywood MT 59254 Phone: (406) 765-2310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4606278	Sheridan County	100 W Laurel Ave	Plentywood	59254	(406) 765-2310

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S2 Currently in Use	1911	9/1/1995 10 / No	Heating Oil 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Gravity Feed	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Sheridan County 100 W Laurel Ave Plentywood MT 59254 Phone: (406) 765-2310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4606279	Sheridan County Shop	MT Highway 16 E	Plentywood	59254	(406) 765-1221

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	1912	1/1/1990 16 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1913	1/1/1990 16 / No	Diesel 10,150	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	1914	1/1/1990 16 / No	Diesel 10,150	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1915	1/1/1990 16 / No	Used Oil 1,002	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Farmers Union Oil Co Plentywood 301 W 1st Ave Plentywood MT 59254 Phone: (406) 765-1171

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4606801	Farmers Union Oil Co Plentywood	301 W 1st Ave	Plentywood	59254	(406) 765-1171

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
8 / 09 Currently in Use	1038	6/1/1996 10 / No	Gasoline 20,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
9 / 10 Currently in Use	1039	6/1/1996 10 / No	Diesel 20,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
10 / 11 Currently in Use	1040	6/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
11 / 12 Currently in Use	1041	6/1/1996 10 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
12 / 13 Currently in Use	1042	6/1/1996 10 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
13 / 14 Currently in Use	1043	6/1/1996 10 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					
14 / 15 Currently in Use	1044	6/1/1996 10 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>●</td><td></td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	●	●	E	F	G	H	I	J	K	L	B		●		E	F	●	H	I	J	K	L	Yes Yes Yes Yes
A	B	●	●	E	F	G	H	I	J	K	L																					
B		●		E	F	●	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Miller Oil Co Inc PO Box 408 Culbertson MT 59218 Phone: (406) 787-6271

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4608609	Miller Oil Co Inc E Railroad Ave	416 W Railroad Ave	Plentywood	59254	(406) 765-2852

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / S1 Currently in Use	1617	4/8/1967 39 / Ye	Diesel 12,048	Asphalt Coated or Bare Steel None	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / S2 Currently in Use	1618	4/7/1961 45 / Ye	Gasoline 5,327	Asphalt Coated or Bare Steel None	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
3 / S3 Currently in Use	1619	4/8/1967 39 / Ye	Gasoline 14,848	Asphalt Coated or Bare Steel None	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
4 / S4 Currently in Use	1620	4/7/1968 38 / Ye	Diesel 14,773	Asphalt Coated or Bare Steel None	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Montana Pioneer Manor Inc 506 Glenwood Ave Plentywood MT 59254 Phone: (406) 765-1400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4610679	Montana Pioneer Manor Inc	605 Sheridan St	Plentywood	59254	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S2 Currently in Use	1673	5/1/1996 10 / No	Heating Oil 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (B) (D) (E) (F) (●) (H) (I) (●) (K) (L) </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Sheridan County 100 W Laurel Ave Plentywood MT 59254 Phone: (406) 765-2310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4612330	Sherwood Airport 4612330	100 West Laurel Ave	Plentywood	59254	(406) 765-2310

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1916	1/1/1989 17 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1917	1/1/1989 17 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: MNLC Inc Can Am Stores 203 Raymond Road Plentywood MT 59254 Phone: (406) 765-2121

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4612667	MNLC Inc Can Am Stores	203 Raymond Road	Plentywood	59254	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	2954	7/1/1991 15 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
2 / 02 Currently in Use	2955	7/1/1991 15 / No	Diesel 10,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Sheridan

Owner Name and Address: Jacks Service PO Box 165 Reserve MT 59258 Phone: (406) 286-5276

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4602103	Jacks Service	101 Main St	Reserve	59258	(406) 286-5465

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
3 / 03 Currently in Use	4733	5/21/1991 15 / No	Gasoline 2,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B			D	E	F	G	H	I	●	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B			D	E	F	G	H	I	●	K	L																					
5 / 05 Currently In Use	4213	7/27/2000 05 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B			D	E	F	G	H	I	●	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B			D	E	F	G	H	I	●	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed